

December 2019 Activity:

Construction: Kuhns – Filter sock removal, Shaw – Filter sock removal, and Mamont South 1 – Filter sock removal

Drilling: No activity

Completions: Monitoring Shaw wells while working with PADEP on path forward on the Shaw Pad.

Facilities: No activity

Production: No activity

Midstream: No activity

Plugging: No activity