

July 2018 Activity:

Construction: Shaw Pad – Drilling support; Hutchinson – Road repair and reclamation touch up; Kuhns – Survey/Reclamation; DeArmitt – Survey/Reclamation; Gaut – Survey/Reclamation; Mamont South 1 – Roadway repair for permit termination; Aikens – Topsoil rework/Borrow for Mamont South 1

Drilling: Spud and drill Shaw 1H, walk rig to 1G and 1J wells after completion at 1H

Completions: No activity

Facilities: No activity

Production: Hutchinson Pad – Two days of slickline work

Midstream: No activity