

June 2019 Activity:

**Construction:** Gaut – Post construction storm water management BMP installation;  
Shaw - Post construction storm water management BMP installation

**Drilling:** No activity

**Completions:** Monitoring Shaw 1G well while working with PADEP on path forward on the Shaw Pad.

**Facilities:** No activity

**Production:** Continue installing plunger lift system on the Hutchinson pad

**Midstream:** Completing installation of pipeline and restoration of the Shaw pipeline

**Plugging:** Reclaiming King Nugget orphan well found approximately 930' north of the Shaw Pad – 40.506464, -79.572459. Plugging MAWC Gumbert #5-Tract #36 well.