

Mamont Oil Spill and Reporting  
April 22, 2014

This afternoon a trailer belonging to a company called Mobil Mini was at the station to haul out a Conex Box that was used by the electrical contractor during construction. While attempting to load the Conex on a trailer a hydraulic line for the winch broke and sprayed oil on the operator and ground. The station operator said that it affected an area around 8ft to 10ft in diameter. Oil soap pads and absorbent material were immediately applied to the area and the spill was contained to the affected area. It was estimated that less than 1 gallon of oil was sprayed on the ground.

DEP was notified and the spill was cleaned up.