

Below, please find an update for the most recent activity at MAWC.....

GAUT 4I – Drilling ahead. Conductor, Surface, all Intermediate casings have been cemented in place. Ready to drill out casing shoe and start to drill lateral section.

Safety meetings were performed with all contractors on site. No spills or environmental issues to report. The site is neat and orderly, and all E&S controls are in place.